

THE UNITED KINGDOM VEHICLE APPROVAL AUTHORITY

COMMUNICATION CONCERNING THE APPROVAL GRANTED (1) LAPPROVAL EXTENDED (1) APPROVAL REFUSED (1) LAPPROVAL WITHDRAWN (1) LAPPROVAL DISCONTINUED (1) OF A REPLACEMENT BRAKE DISC OR A REPLACEMENT BRAKE DRUM PURSUANT TO REGULATION NO. 90.02

E11

Approval No:

E11 90R-02C0986/18127

Extension No:

Not Applicable

Reason(s) for Extension:

Not Applicable

- Applicant's name and address:
 Meritor Aftermarket Switzerland AG,
 Neugutstrasse 89,
 8600 Dubendorf,
 Switzerland
- 2. Manufacturer's name and address
 Meritor Aftermarket
 Neugutstrasse 89,
 8600 Dubendorf,
 Switzerland
- Make and type of brake disc/drum:
 MBR5016HD (Tested), MBR5025, MBR6036,
 MBR6037, MBR5057, MBR5046,
 MBR5105, MBR5048, MBR5183,
 MBR5128, MBR5184, MBR5068,
 MBR5064, MBR5074, MBR5032,
 MBR5171, MBR5179, MBR5015,
 MBR5076, MBR5063, MBR5143

Interchangeable Disc Front and Rear (Top hat/Vented/Pillar) SAE / J431 / 1996 /G3000, ASTM A159-83/3000

4. Vehicles/axles/brakes for which the replacement brake disc or a replacement brake drum is approved:

See manufacturers documents

Job Number VSN264287



5. Submitted for approval on: 01 September 2012

6. Technical service responsible for approval tests: Vehicle Certification Agency

6.1. Date of test report: 13 December 2013

6.2. Number of test report: VSN264211

7. Approval GRANTED/REFUSED/EXTENDED/WITHDRAWN (11)

8. Place: BRISTOL

9. Date: 03 MARCH 2014

10. Signature:

A. W. STENNING Head of Technical and Quality Support Group

11. Annexed to this communication is a list of documents in the approval file deposited at the administrative services having delivered the approval and which can be obtained upon request.

(1) Strike out what does not apply.

